

R44

Page 1 of 1

SERVICE BULLETIN SB-70

DATE: 25 March 2009

TO: R44 Owners, Operators, and Service Centers

SUBJECT: Carbon Monoxide (CO) Detector Retrofit

ROTORCRAFT AFFECTED: R44 Helicopters S/N 0001 thru 1590.

TIME OF COMPLIANCE: Within next 100 flight hours or by 31 July 2009, whichever occurs first.

BACKGROUND: Carbon monoxide poisoning can be fatal. This bulletin requires installing CO detectors on helicopters that do not already have a detector.

COMPLIANCE PROCEDURE:

1. Determine if caution light labeled "Carbon Monoxide" is installed; if installed, no further action is required.
2. If "Carbon Monoxide" caution light is not installed, order KI-164 kit from RHC Customer Service (via RHC web site or by phone). Install per kit instructions. Kit instructions are available online at: www.robinsonheli.com/servelib.htm.

Approximate Cost:

Parts: \$175 for KI-164 kit if ordered by 31 July 2009.

Order must include helicopter serial number.

Labor: 2 man-hours.