



**Pricing for R22 2200-Hour Maintenance and Inspection Performed at RHC**

Below pricing for R22 2200-Hour Maintenance and Inspection performed at RHC effective **9 April 2024**. Base price is for an airworthy R22 properly maintained, undamaged and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400-hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes the 2200-Hour engine overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2200-hours:

**Exchange Components**

**New Parts**

A006 MR Gearbox	A016 MR Blades	A170 Sheave
A017 Swashplate	A027 Cooling Panels	A190 Drive V-Belts
A018 Clutch	A029 TR Blades	A258 MR Pitch Links
B021 TR Gearbox	A031 TR Pitch Control	A274 Windshields
A051 Actuator	A041 Damper Bearing	A667 Skid Shoes
B174 Fanwheel	A120 Bellcrank	A947 Flex Plates
Engine	A121-17 P/P Tube	A007 Fan Shaft & Bearing
	A158 Spindles	Shell, Fuel Tanks
	A159 Pitch Bearings	Various small parts & hardware
	A169 Muffler	

**Base Price, all R22 Models (does not include upgrades)..... \$207,000.00 + upgrades**

<b>Applicability</b>	<b>Description</b>	<b>Price</b>
Required	B338-2 ICS Control (VOX & music Input)	\$2,840.00
Required	KI-160 Full-Flow Oil Filter	\$615.00
Required	KI-217-1 Fuel Bladder Tanks	\$13,700.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
<b>Required</b>	<b>KI-275 Cockpit Camera</b>	<b>\$3,800.00</b>
Mariners	A034-1 Fixed Float Overhaul (includes new floats)	\$45,000.00
Optional	C058-5 Cyclic Pistol Grip	\$4,830.00
Optional	B084-1 Impact Resistant Windshields	\$18,750.00
Optional, S/N's 0501 thru 2570	Lycoming O-320 to O-360 Engine (new) Upgrade	\$65,000.00

**Base price also includes:**

Complete refurbishing of helicopter interior including new seats (velour), carpet (charcoal only) and headliner. Additional cost for leather seats is \$830.00.

Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs). Crating \$5,000.00.

Production-equivalent minor upgrades and up-to-date Service Bulletin compliance.

The RHC Limited Parts Warranty covers parts replaced, repaired and/or overhauled for a period of 1-year or 1000-hours, whichever event occurs first; provided, the part has been subjected to normal use and service.